



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other								
5	DEEC DOWNLOAD	Work Card Task Card		03-Dec-2009 H: 10276.40 L: 7948	L: 35			L: 7983	L: 15
	482		Airframe						
5 05E1-150	200 HOUR INSPECTION NO.1 ENGINE	Work Card Task Card		03-Dec-2009 H: 10106.90	H: 200			H: 10306.90	H: 180.80
	263		Engine 1						
5 05E1-300	400 HOUR INSPECTION NO.1 ENGINE	Work Card Task Card		03-Dec-2009 H: 10106.90	H: 400			H: 10506.90	H: 380.80
	264		Engine 1						
5 05E1-800	800 HOUR INSPECTION NO.1 ENGINE	Work Card Task Card		17-Jun-2008 H: 9763.00	H: 800			H: 10563.00	H: 436.90
	265		Engine 1						
5 05E2-150	200 HOUR INSPECTION NO.2 ENGINE	Work Card Task Card		28-Aug-2009 H: 9353.20 L: 7265	H: 200			H: 9553.20	H: 112.50
	285		Engine 2						
5 05E2-300	400 HOUR INSPECTION NO.2 ENGINE	Work Card Task Card		28-Oct-2008 H: 9156.40	H: 400			H: 9556.40	H: 115.70
	286		Engine 2						
5 05E2-800	800 HOUR INSPECTION NO.2 ENGINE	Work Card Task Card		28-Oct-2008 H: 9156.40	H: 800			H: 9956.40	H: 515.70
	288		Engine 2						
5 10-00 PHASE A	PHASE A1 - A6	Work Card Task Card		18-Feb-2009 H: 10080.00 L: 7830	M: 12 H: 300			18-Feb-2010 H: 10380.00	D: 9 H: 84.40
	1		Airframe						
5 10-00 PHASE B	PHASE B1 - B6	Work Card Task Card		18-Feb-2009 H: 10080.00 L: 7830	M: 24 H: 600		M: 0 H: 0.00	18-Feb-2011 H: 10680.00	M: 12 D: 9 H: 384.40
	8		Airframe						





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
5 10-00 PHASE C 14	PHASE C1 - C6	Work Card Task Card	Airframe	18-Feb-2009 H: 10080.00 L: 7830	M: 48 H: 1200		M: 0 H: 0.00	18-Feb-2013 H: 11280.00	M: 36 D: 9 H: 984.40
5 10-00 PHASE D 20	PHASE D1 - D6	Work Card Task Card	Airframe	24-Apr-2006 H: 8890.50 L: 6749	M: 96 H: 2400		M: 0 H: 0.00	24-Apr-2014 H: 11290.50	M: 50 D: 15 H: 994.90
5 10-25 26	3000 LANDING INSP	Work Card Task Card	Airframe	05-Jun-2002 H: 8028.30 L: 5822	L: 3000		L: 0	L: 8822	L: 854
5 10-26 27	MAJOR LANDING GEAR INSP	Work Card Task Card	Airframe	30-Oct-2003 H: 8451.70 L: 6278	L: 6000		L: 0	L: 12278	L: 4310
5 10-27 28	12YR/6000 LAND AIRFRAME INSP	Work Card Task Card	Airframe	30-Oct-2003 H: 8451.70 L: 6278	M: 144 L: 6000		M: 0 L: 0	30-Oct-2015 L: 12278	M: 68 D: 21 L: 4310
5 10-28 29	12000 HOUR AIRFRAME INSP	Work Card Task Card	Airframe	07-Mar-1979	H: 12000		H: 0.00	H: 12000.00	H: 1704.40
8 0001 246	AIRCRAFT WEIGHT & BALANCE	Work Card	Airframe	18-Feb-2009 H: 10080.00 L: 7830	M: 36			18-Feb-2012	M: 24 D: 9
12 D1223001 498	PERFORM NI-CAD EMERGENCY POWER SUPPLY BATTERY DISCHARGE / RECHARGE (REFER TO 12-23-01)	Work Card	Airframe		M: 12				
21 H2130007 53	CABIN PRESSURIZATION SYSTEM-PERFORM CABIN LEAK RATE CHECK	Work Card	Airframe	18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
23	ARTEX/ELT 12 YEAR INSPECTION	Work Card		08-Dec-2003	M: 144			08-Dec-2015	M: 69 D: 29
480			Airframe						
23	CVR OPS CHECK	Work Card		09-Apr-2009	M: 12			09-Apr-2010	M: 2
479			Airframe						
23 F2565000	CLEAN/TEST CVR ULB SWITCH/BATTERY	Work Card		01-May-2008	M: 24		D: -7	24-Apr-2010	M: 2 D: 15
64	P/N: GA100-0000 S/N: 00241		Airframe						
23 F2566000	REPLACE CVR UNDERWATER LOCATOR BEACON BATTERY	Work Card		24-Apr-2006				30-Mar-2012	M: 25 D: 21
63	P/N: DK120 S/N: DU52224		Airframe						
24 B2432010-01	NO.1 BATTERY INSTALLATION INSPECTION	Work Card		28-Aug-2009	M: 6			28-Feb-2010	D: 19
41			Airframe						
24 B2432010-02	NO.2 BATTERY INSTALLATION INSPECTION	Work Card		28-Aug-2009	M: 6			28-Feb-2010	D: 19
42			Airframe						
24 C2431015-01	NO.1 GENERATOR-(OVERHAUL)	Work Card		05-Oct-2007 H: 9467.20	H: 2000		H: 0.00	H: 11467.20	H: 1171.60
54	P/N: 30B107-19A S/N: 2729		Airframe						
24 C2431015-02	NO.2 GENERATOR- (OVERHAUL)	Work Card		29-Aug-2007 H: 9424.20	H: 2000		H: 0.00	H: 11424.20	H: 1128.60
56	P/N: 30B107-19A S/N: 653		Airframe						
24 C2431016-01	REPLACE NO.1 GENERATOR BEARINGS	Work Card		05-Oct-2007 H: 9467.20	H: 1050			H: 10517.20	H: 221.60
55			Airframe						
24 C2431016-02	REPLACE NO.2 GENERATOR BEARINGS	Work Card		29-Aug-2007 H: 9424.20	H: 1050			H: 10474.20	H: 178.60
57			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other								
24 E1222000-01	NO.1 BATTERY 37 P/N: RG-380EMY S/N: 40159691	Work Card		03-Nov-2009 H: 10242.10 L: 7929	M: 3 H: 200		M: 0 H: 0.00	03-Feb-2010 H: 10442.10	D: -6 H: 146.50
24 E1222000-02	NO.2 BATTERY 38 P/N: RG380EMY S/N: 40135525	Work Card		03-Nov-2009 H: 10242.10 L: 7929	M: 3 H: 200		M: 0 H: 0.00	03-Feb-2010 H: 10442.10	D: -6 H: 146.50
24 F1223010-01	NO.1 EMERGENCY POWER SUPPLY OPS CHECK 49 P/N: 501-1228-04 S/N: 7643	Work Card		08-Oct-2009 H: 10229.80 L: 7922	M: 6		M: 0	08-Apr-2010	M: 1 D: 30
24 F1223015-01	NO.1 EMERGENCY POWER SUPPLY DISCHARGE CHECK 47 P/N: 501-1228-04 S/N: 7643	Work Card		08-Oct-2009 H: 10229.80 L: 7922	M: 12		M: 0	08-Oct-2010	M: 7 D: 29
24 G2431045	REPL RIGHT ESSENTIAL A/B BUS(40A) CBS 131	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
24 G2431047	REPL LEFT ESSENTIAL A/B BUS(40A) CBS 130	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
24 G2431049	REPL MAIN BUS TIE /PWR BUS TIE(50A) CB 132	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
24 H2431017-01	NO.1 BATTERY CABLES AND RECEPTACLE CONNECTOR INSPECTION 43	Work Card		18-Feb-2009 H: 10080.00	H: 300			H: 10380.00	H: 84.40
24 H2431017-02	NO.2 BATTERY CABLES AND RECEPTACLES CONNECTOR INSPECTION 44	Work Card		18-Feb-2009 H: 10080.00	H: 300			H: 10380.00	H: 84.40



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
25	FIRST AID KIT INSPECTION	Work Card		14-May-2009 H: 10148.60 L: 7870	M: 12			14-May-2010	M: 3 D: 5
481			Airframe						
25 C2561000	LIFE VESTS	Work Card		05-Mar-2005	M: 60			05-Mar-2010	D: 24
472	P/N: PO723E1050		Airframe						
25 E2562001	FUNCTIONAL TEST DRAG CHUTE	Work Card		08-Oct-2009 H: 10229.80 L: 7922	M: 6			08-Apr-2010	M: 1 D: 30
98			Airframe						
25 E2564001	REPLACE ELT BATTERY	Work Card		02-May-2008 H: 9785.50	M: 72			02-May-2014	M: 50 D: 23
60			Airframe						
25 J2563001	INSPECT ELT BATTERY FT ELT SYSTEM FAR 91.207(D) 1-4	Work Card		14-May-2009 H: 10148.60 L: 7870	M: 12			14-May-2010	M: 3 D: 5
59	P/N: 453-5002-366 S/N: 04768		Airframe						
26	COCKPIT PORTABLE FIRE EXTINGUISHER 6 YEAR INSPECTION	Work Card			M: 72		M: 0	30-Dec-2011	M: 22 D: 21
474	P/N: A1600 S/N: A569292		Airframe						
26	COCKPIT PORTABLE FIRE EXTINGUISHER WEIGHT CHECK	Work Card		12-Feb-2009	M: 12		M: 0	12-Feb-2010	D: 3
473	P/N: A1600 S/N: A569292		Airframe						
26	INSPECT COCKPIT FIRE EXT	Work Card		01-Feb-2010	M: 1			01-Mar-2010	D: 20
420			Airframe						
26 B2620005-01	CHK NO.1 ENG FIRE EXT PRESS GUAGE	Work Card		28-Aug-2009	M: 6			28-Feb-2010	D: 19
99			Airframe						





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other								
26 B2620005-02	CHK NO.2 ENG FIRE EXT PRESS GUAGE	Work Card		28-Aug-2009	M: 6			28-Feb-2010	D: 19
100			Airframe						
26 C2620025-01	HYDRO TEST NO.1 ENG FIRE EXT CONT	Work Card		01-Mar-2007 H: 9186.60 L: 7009	M: 60		M: 0	01-Mar-2012	M: 24 D: 21
105	P/N: 30402102-1 S/N: 27103b1		Airframe						
26 C2620025-02	HYDRO TEST NO.2 ENG FIRE EXT CONT	Work Card		05-Jun-2006 H: 8895.10 L: 6754	M: 60		M: 0	05-Jun-2011	M: 15 D: 27
106	P/N: HTL30402102-1 S/N: B2018		Airframe						
26 C2620030-01	HYDRO TEST COCKPIT PORTABLE FIRE EXTINGUISHER	Work Card			M: 144		M: 0	30-Dec-2017	M: 94 D: 21
31			Airframe						
26 E2620040-01	LEFT NO.1 FIRE EXT SQUIBB	Work Card		01-Mar-2007	M: 72			01-Mar-2013	M: 36 D: 20
107			Airframe						
26 E2620040-02	LEFT NO.2 FIRE EXT SQUIBB	Work Card		01-Mar-2007	M: 72			01-Mar-2013	M: 36 D: 20
108			Airframe						
26 E2620040-03	RIGHT NO.1 FIRE EXT SQUIBB	Work Card		08-Jun-2007	M: 72			08-Jun-2013	M: 39 D: 30
109			Airframe						
26 E2620040-03	RIGHT NO.2 FIRE EXT SQUIBB	Work Card		08-Jun-2007	M: 72			08-Jun-2013	M: 39 D: 30
110			Airframe						
27 E2710010-01	REPL LEFT AIL DRIVE YOKE BOLT (NAS1104-38D)	Work Card		12-Dec-2007 H: 9578.10	H: 3600			H: 13178.10	H: 2882.50
191			Airframe						





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other								
27 E2710010-02	REPL RIGHT AIL DRIVE YOKE BOLT (NAS1104-38D)	Work Card		12-Dec-2007 H: 9578.10	H: 3600			H: 13178.10	H: 2882.50
192			Airframe						
27 E2710014-01	REPL LEFT AIL CNTR HINGE BOLT (AN4H13A)	Work Card		30-Oct-2003 H: 8451.70 L: 6278	H: 3600			H: 12051.70	H: 1756.10
193			Airframe						
27 E2710014-02	REPL RIGHT AIL CNTR HINGE BOLT (AN4H13A)	Work Card		30-Oct-2003 H: 8451.70 L: 6278	H: 3600			H: 12051.70	H: 1756.10
194			Airframe						
27 E2710020-01	REPL LEFT AIL CLEVIS BOLT (NAS464P4)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
197			Airframe						
27 E2710020-02	REPL RIGHT AIL CLEVIS BOLT (NAS464P4)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
198			Airframe						
27 E2710021-01	REPL LEFT AIL INBD/OUTBD HINGE BOLTS (AN4H11A)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
199			Airframe						
27 E2710021-02	REPL RIGHT AIL INBD/OUTBD HINGE BOLTS (AN4H11A)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
200			Airframe						
27 E2710022-01	REPL LEFT AIL SECTOR (5425015)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
201			Airframe						
27 E2710022-02	REPL RIGHT AIL SECTOR (5425015)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
202			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
27 E2710023-01	REPLACE LEFTAILERON PULLEY ASSEMBLY	Work Card			H: 20000			H: 20000.00	H: 9704.40
454			Airframe						
27 E2710023-02	REPLACE RIGHTAILERON PULLEY ASSEMBLY	Work Card			H: 20000			H: 20000.00	H: 9704.40
455			Airframe						
27 E2710025-01	REPL LEFTAIL CLEVIS (2324512/2324517)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
203			Airframe						
27 E2710025-02	REPL RIGHTAIL CLEVIS (2324512/2324517)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
204			Airframe						
27 E2710027-01	REPL LEFTAIL YOKE ASSY (2324511)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
205			Airframe						
27 E2710027-02	REPL RIGHTAIL YOKE ASSY (2324511)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
206			Airframe						
27 E2710029-01	REPL LEFTAIL BEARING SUP ASSY (2324505/2324510)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
207			Airframe						
27 E2710029-02	REPL RIGHTAIL BEARING SUP ASSY (2324505/2324510)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
208			Airframe						
27 E2710031-01	REPL LEFTAIL HINGE BRKT ASSY (2322530)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
209			Airframe						
27 E2710031-02	REPL RIGHTAIL HINGE BRKT ASSY(2322530)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
210			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
27 E2720018	RUDDER ASSEMBLY	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
134			Airframe						
27 E2720021	REPL RUDDER HINGE BOLTS	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
135			Airframe						
27 E2720023	REPL RUDDER LOWER BEARING ASSEMBLY(2312040)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
448			Airframe						
27 E2720024	REPL RUDDER HINGE ASSEMBLY, UPPER (2331030)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
449			Airframe						
27 E2720025	REPL RUDDER HINGE ASSEMBLY, CENTER (2331031)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
450			Airframe						
27 E2730016	ELEVATOR ASSEMBLY	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
139			Airframe						
27 E2730020	REPL ELEV HINGE BRKTS	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
140			Airframe						
27 E2730021	REPL ELEVATOR BELLCRANKS	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
141			Airframe						
27 E2730023	REPL ELEV UPPER PUSH/PULL TUBES	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
142			Airframe						
27 E2730024	REPL ELEV HINGE BOLTS	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
143			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
27 E2730027	REPL ELEVATOR DOWNSPRING ASSEMBLY ATTACH BOLT (AN23-16)	Work Card		10-May-1999 H: 6963.50 L: 4894	M: 144 L: 6000			10-May-2011 L: 10894	M: 15 D: 1 L: 2926
452			Airframe						
27 E2740010	REPL HORIZ STAB HINGE PIN	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
144			Airframe						
27 E2750002-01	REPL LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	Work Card		18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
211			Airframe						
27 E2750002-02	REPL RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	Work Card		18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
212			Airframe						
27 E2750015-01	LEFT FLAP ASSEMBLY	Work Card			H: 19300			H: 19300.00	H: 9004.40
456 P/N: 2325010			Airframe						
27 E2750015-01	RIGHT FLAP ASSEMBLY	Work Card			H: 19300			H: 19300.00	H: 9004.40
457 P/N: 2325010			Airframe						
27 E2750021-01	REPL LEFT INBD FLAP TRACK ASSY (2325022)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
217			Airframe						
27 E2750021-02	REPL LEFT OUTBD FLAP TRACK ASSY (2325022)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
218			Airframe						
27 E2750021-03	REPL RIGHT INBD FLAP TRACK ASSY(2325022)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
219			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
27 E2750021-04	REPL RIGHT OUTBD FLAP TRACK ASSY (2325022)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
220			Airframe						
27 E2750023-01	REPL LEFT FLAP INBD NOSE ROLLER TRACK (2322511)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
221			Airframe						
27 E2750023-02	REPL RIGHT FLAP INBD NOSE ROLLER TRACK (2322511)	Work Card		18-Feb-2009 H: 10080.00	H: 20000		H: 0.00	H: 30080.00	H: 19784.40
222 P/N: 2322511-27			Airframe						
27 E2750024-01	REPL LEFT FLAP OUTBD NOSE ROLLER TRACK (2322512)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
223			Airframe						
27 E2750024-02	REPL RIGHT FLAP OUTBD NOSE ROLLER TRACK (2322512)	Work Card		18-Feb-2009 H: 10080.00	H: 20000		H: 0.00	H: 30080.00	H: 19784.40
224 P/N: 2322512-37			Airframe						
27 E2760066-01	REPL LEFT SPOILER ACTUATOR 1/4" BOLT (NAS464P4)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
458			Airframe						
27 E2760066-02	REPL RIGHT SPOILER ACTUATOR 1/4" BOLT (NAS464P4)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
459			Airframe						
27 E2760067-01	REPL LEFT 5/16" SPOILER ATTACH BOLTS (NAS464P5)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
227			Airframe						
27 E2760067-02	REPL RIGHT 5/16" SPOILER ATTACH BOLTS (NAS464P5)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
228			Airframe						
27 E2760068-01	REPL LEFT SPOILER PIVOT BOLT (NAS464P5)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
234			Airframe						





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
27 E2760068-02	REPL RIGHT SPOILER PIVOT BOLT(NAS464P5)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
	235		Airframe						
27 E2760069-01	LEFT SPOILER ASSY	Work Card		25-Jul-2000 H: 7462.90 L: 5293	H: 9000		H: 0.00	H: 16462.90	H: 6167.30
	229 P/N: 2492001-3 S/N: W1349S		Airframe						
27 E2760069-02	RIGHT SPOILER ASSY	Work Card		25-Jul-2000 H: 7462.90 L: 5293	H: 9000		H: 0.00	H: 16462.90	H: 6167.30
	230 P/N: 2492001-4 S/N: W1350S		Airframe						
27 E2760071-01	REPL LEFT SPOILER ACT ARM ASSY(2422511)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
	231 P/N: 24225-043		Airframe						
27 E2760071-02	REPL RIGHT SPOILER ACT ARM ASSY(2422511)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
	232 P/N: 24225-043		Airframe						
27 E2760074-01	REPL LEFT SPOILER ACTUATOR AFT BOLT (NAS464P4)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
	238		Airframe						
27 E2760074-02	REPL RIGHT SPOILER ACTUATOR AFT BOLT (NAS464P4)	Work Card		24-Apr-2006 H: 8890.50	H: 9000			H: 17890.50	H: 7594.90
	239		Airframe						
27 E2760075-01	LEFT SPOILER ACTUATOR ASSY	Work Card			H: 20000		H: 8883.20	H: 11116.80	H: 821.20
	242 P/N: 2417015-5		Airframe						
27 E2760075-02	RIGHT SPOILER ACTUATOR ASSY	Work Card			H: 20000		H: 8883.20	H: 11116.80	H: 821.20
	243 P/N: 2417015-5		Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
27 E2760076-01	REPL LEFT SPOILER ACT FITTING AND BOLT (BACB30NJ4D)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
240			Airframe						
27 E2760076-02	REPL RIGHT SPOILER ACT FITTING AND BOLT (BACB30NJ4D)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
241			Airframe						
27 F2710009	REPLACE AILERON CONTROL CABLES	Work Card		24-Apr-2006 H: 8890.50	H: 2400			H: 11290.50	H: 994.90
190			Airframe						
27 F2720012	REPL PRIMARY RUDDER CNTRL CABLES	Work Card		24-Apr-2006 H: 8890.50	H: 2400			H: 11290.50	H: 994.90
133			Airframe						
27 F2730015	REPL PRIMARY ELEV CNTRL CABLES	Work Card		24-Apr-2006 H: 8890.50	H: 2400			H: 11290.50	H: 994.90
138			Airframe						
27 F2750017-01	REPL LEFT INBD FLAP HINGE FITTING (ON FLAP)(2625023)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
213			Airframe						
27 F2750017-02	REPL RIGHT INBD FLAP HINGE FITTING (ON FLAP)(2625023)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
214			Airframe						
27 F2750019-01	REPL LEFT OUTBD FLAP HINGE FITTING (ON FLAP)(2625024)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
215			Airframe						
27 F2750019-02	REPL RIGHT OUTBD FLAP HINGE FITTING (ON FLAP)(2625024)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
216			Airframe						
27 G2710016-01	LEFT AILERON ASSY	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
195			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
27 G2710016-02	RIGHT AILERON ASSY	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
196			Airframe						
27 G2740011-01	REPL UPPER HORIZ STAB ACT ATTACH BOLTS	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
145			Airframe						
27 G2740011-02	REPL LOWER HORIZ STAB ACT ATTACH BOLTS	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
146			Airframe						
27 G2750034-01	REPL LEFT WING FLAP SECTOR MTG BOLT (NAS1305-42H)	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
225			Airframe						
27 G2750034-02	REPL RIGHT WING FLAP SECTOR MTG BOLT (NAS1305-42H)	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
226			Airframe						
27 H2740021	HORIZONTAL STABILIZER ACTUATOR-PERFORM OVERHAUL	Work Card		05-Jan-2009 H: 10064.80	H: 600		H: 0.00	H: 10664.80	H: 369.20
66 P/N: 2332540-214 S/N: 197			Airframe						
27 H2750044-01	INSP LEFT FLAP CAM FOLLOW BEARINGS	Work Card		18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
113			Airframe						
27 H2750044-02	INSP RIGHT FLAP CAM FOLLOW BEARINGS	Work Card		18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
114			Airframe						
28 G2820002	REPL FUEL HOSE ASSYS-12YR	Work Card		22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
127			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
28 G7110021 147	REPL ENG NACELLE FUEL HOSES- 5 YR	Work Card	Airframe	24-Apr-2006 H: 8890.50	M: 60 H: 2400			24-Apr-2011 H: 11290.50	M: 14 D: 15 H: 994.90
28 K2812001 460	REPLACE TIP TANK FLAPPER VALVES (2323006-5)	Work Card	Airframe	24-Apr-2006	M: 60			24-Apr-2011	M: 14 D: 15
28 L2812011-01 117	INSPECTION LEFT WING TIP TANK	Work Card	Airframe	02-May-2008	M: 24			02-May-2010	M: 2 D: 23
28 L2812011-02 118	INSPECTION RIGHT WING TIP TANK	Work Card	Airframe	02-May-2008	M: 24			02-May-2010	M: 2 D: 23
28 L2812020-01 119	INSP LEFT WING FLAP VALVES WS 53 INBD WS 0.0	Work Card	Airframe	18-Feb-2009 H: 10080.00	M: 24			18-Feb-2011	M: 12 D: 9
28 L2812020-02 120	INSP RIGHT WING FLAP VALVES WS 53 INBD WS 0.0	Work Card	Airframe	18-Feb-2009 H: 10080.00	M: 24			18-Feb-2011	M: 12 D: 9
29 G2900001 128	REPL HYD HOSE ASSYS-12YR	Work Card	Airframe	22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
29 G7110022 148	REPL ENG NACELLE HYD HOSES- 5 YR	Work Card	Airframe	24-Apr-2006 H: 8890.50	M: 60 H: 2400			24-Apr-2011 H: 11290.50	M: 14 D: 15 H: 994.90
32 500	RIGHT GEAR DOWN SAFETY SWITCH AND ANTISKID ELECTRICAL CONTACTS FUNCTIONAL CHECK	Work Card	Airframe	23-Nov-2009 H: 10263.40	H: 1200		H: 0.00	H: 13,263.40	H: 2967.80



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
32 C3255001	INSP NOSE WHEEL STEER ACTUATOR 88 P/N: 2332540-214 S/N: 130	Work Card	Airframe	05-Oct-2007 H: 9467.20	H: 2000		H: 0.00	H: 11467.20	H: 1171.60
32 E3211070-01	LEFT MLG STRUT 178 P/N: 2341100-13 S/N: 2526	Work Card	Airframe		L: 9000		L: 0	L: 9000	L: 1032
32 E3211070-02	RIGHT MLG STRUT 179 P/N: 2341100-14 S/N: 2516	Work Card	Airframe		L: 9000		L: 0	L: 9000	L: 1032
32 E3211072-01	REPL LEFT MAIN GEAR ATTACH PIN (2341109) 176	Work Card	Airframe	07-Mar-1979	L: 9000			L: 9000	L: 1032
32 E3211072-02	REPL RIGHT MAIN GEAR ATTACH PIN (2341109) 177	Work Card	Airframe	07-Mar-1979	L: 9000			L: 9000	L: 1032
32 E3211080-01	LEFT MAIN GEAR PILLAR ACT ASSY 180 P/N: 2341123-1/14 S/N: UNK	Work Card	Airframe	07-Mar-1979	L: 18000		L: 0	L: 18000	L: 10032
32 E3211080-02	RIGHT MAIN GEAR PILLAR ACT ASSY 181 P/N: 2341123-1/14 S/N: UNK	Work Card	Airframe	07-Mar-1979	L: 18000		L: 0	L: 18000	L: 10032
32 E3211082	NLG STRUT 182 P/N: 2342100-7 S/N: 2473	Work Card	Airframe		L: 20000		L: 6746	L: 13254	L: 5286
32 E3211083	NLG ACTUATOR 183 P/N: 2317100-5 S/N: 2540	Work Card	Airframe		L: 20000		L: 6746	L: 13254	L: 5286
32 E3211087-01	LEFT MLG ACTUATOR 184 P/N: 2327100 S/N: 3029	Work Card	Airframe		L: 20000		L: 6746	L: 13254	L: 5286



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
32 E3211087-02	RIGHT MLG ACTUATOR 185 P/N: 2327100-031 S/N: 0153	Work Card	Airframe		L: 20000		L: 6746	L: 13254	L: 5286
32 G3210003	REPL LAND GEAR HYDR HOSES ASSYS 175	Work Card	Airframe	04-Jul-2008 H: 9841.80	M: 60 H: 1500			04-Jul-2013 H: 11341.80	M: 40 D: 25 H: 1046.20
32 G3240040	REPL HYDR BRAKE HOSE ASSYS 188	Work Card	Airframe	24-Apr-2006 H: 8890.50	M: 60 H: 2400			24-Apr-2011 H: 11290.50	M: 14 D: 15 H: 994.90
32 L3233013	REPL EMERGENCY AIR HOSES 187	Work Card	Airframe	22-Jul-2004 L: 6285	M: 144 L: 6000			22-Jul-2016 L: 12285	M: 77 D: 13 L: 4317
34	HONEYWELL KGP-860 ICA 491	Work Card	Airframe	22-Apr-2005	M: 144			22-Apr-2017	M: 86 D: 13
34 0006	CALIBRATE LEFT ALTIMETER 251	Work Card	Airframe	07-Jul-2009 H: 10177.70 L: 7891	M: 24			07-Jul-2011	M: 16 D: 28
34 0007	CALIBRATE RIGHT ALTIMETER 252	Work Card	Airframe	07-Jul-2009 H: 10177.70	M: 24			07-Jul-2011	M: 16 D: 28
34 0008	TEST NO.1 TRANSPONDER 253	Work Card	Airframe	07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28
34 0009	TEST NO.2 TRANSPONDER 254	Work Card	Airframe	07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
34 0010	TEST ADC	Work Card		07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28
255			Airframe						
34 0011	TEST LEFT PITOT/STATIC SYSTEM	Work Card		07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28
256			Airframe						
34 0012	TEST RIGHT PITOT/STATIC SYSTEM	Work Card		07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28
257			Airframe						
34 RVSM	RVSM 10000 HOUR INSPECTION	Work Card		07-Jun-2005 H: 8883.20	H: 10000			H: 18883.20	H: 8587.60
478			Airframe						
34 RVSM	RVSM 144 MONTH INSPECTION	Work Card		07-Jun-2005 H: 8883.20	M: 144			07-Jun-2017	M: 87 D: 29
477			Airframe						
34 RVSM	RVSM 24 MONTH INSPECTION	Work Card		07-Jul-2009	M: 24			07-Jul-2011	M: 16 D: 28
475			Airframe						
34 RVSM	RVSM 96 MONTH INSPECTION	Work Card		07-Jun-2005 H: 8883.20	M: 96			07-Jun-2013	M: 39 D: 29
476			Airframe						
35 C3510001-01	PILOT OXYGEN MASK(EROS)	Work Card		10-Jan-2008	M: 72		M: 0	10-Jan-2014	M: 47 D: 1
35 P/N: MC10-15-101 S/N: 28118			Airframe						
35 C3510001-02	COPILOTS OXYGEN MASK(EROS)	Work Card		22-Aug-2008	M: 72		M: 0	22-Aug-2014	M: 54 D: 13
36 P/N: MC10-15-101 S/N: 57910			Airframe						
35 J3500016	HYDRO TEST OXYGEN CYLINDER	Work Card		28-Aug-2009	M: 60			28-Aug-2014	M: 54 D: 19
71 P/N: 176102 S/N: 38486DH			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
35 Q3510015	COMPLY WITH FACTORY OVERHAUL OF B/E AEROSPACE (PURITAN-BENNET) CREW OXYGEN MASKS (IF INSTALLED)	Work Card			M: 72				
495			Airframe						
36 H3610006-01	BRAKE EMERGENCY AIR BOTTLE	Work Card		30-Sep-1993	M: 480		M: 0	30-Sep-2033	M: 283 D: 21
89 P/N: 23111386 S/N: 550			Airframe						
36 H3610006-02	HYDRO/VIS INSP EMER BOTTLE	Work Card		24-Apr-2006	M: 72			24-Apr-2012	M: 26 D: 15
90			Airframe						
36 H3610006-03	XRAY EMER BOTTLE	Work Card		24-Apr-2006	M: 144			24-Apr-2018	M: 98 D: 15
91			Airframe						
52 L5210025	VIS INSP LWR CAB DOOR STRUCT	Work Card		02-May-2008	M: 24			02-May-2010	M: 2 D: 23
82			Airframe						
53 E5322000	REPL KEELBEAM ATTACH BOLTS	Work Card		30-Oct-2003 H: 8451.70 L: 6278	M: 144 L: 6000			30-Oct-2015 L: 12278	M: 68 D: 21 L: 4310
129			Airframe						
53 J5320006	INSPECT AFT PRESSURE BULKHEAD AT FRAME 22, FS 421.42 FOR CORROSION	Work Card		05-Jun-2002 H: 8028.30 L: 5822	M: 144 L: 6000			05-Jun-2014 L: 11822	M: 51 D: 27 L: 3854
33			Airframe						
54 H5450044-01	EDDY CURRENT INSPECT LEFT ENGINE BEAM SUPPORT FITTINGS	Work Card		04-Jul-2008	M: 144			04-Jul-2020	M: 124 D: 25
444			Airframe						
54 H5450044-02	EDDY CURRENT INSPECT RIGHT ENGINE BEAM SUPPORT FITTINGS	Work Card						30-Oct-2015 L: 12,278.00	M: 68 D: 21 L: 4310
445			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
54 H5450045-01 446	INSPECT LEFT PYLON/ENGINE BEAM SUPPORT STRUCTURE	Work Card	Airframe	04-Jul-2008 H: 9841.80	H: 1400			H: 11241.80	H: 946.20
54 H5450045-02 447	INSPECT RIGHT PYLON/ENGINE BEAM SUPPORT STRUCTURE	Work Card	Airframe	13-Apr-2007 H: 9247.80	H: 1400			H: 10647.80	H: 352.20
54 J5450043-01 111	INSP LEFT PYLON/ENG BEAM STRUCTURE	Work Card	Airframe	04-Jul-2008 H: 9841.80	H: 1400			H: 11241.80	H: 946.20
54 J5450043-02 112	INSP RIGHT PYLON/ENG BEAM STRUCTURE	Work Card	Airframe	13-Apr-2007 H: 9247.80	H: 1400			H: 10647.80	H: 352.20
56 G5610023-01 85	INSP LEFT WINDSHIELD	Work Card	On Condition	05-Oct-2007 H: 9467.20					
	Notes / Compliance	NO LONGER RECURRING							
56 G5610023-02 86	INSP RIGHT WINDSHIELD	Work Card	On Condition	07-Mar-1979					
57 H5750046-01 125	VIS INSP LEFT FLAP SUP FTGS	Work Card	Airframe	18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
57 H5750046-02 126	VIS INSP RIGHT FLAP SUP FTGS	Work Card	Airframe	18-Feb-2009 H: 10080.00 L: 7830	H: 1200			H: 11280.00	H: 984.40
57 L5710035-01 123	INSP LEFT WING INBD DRY BAY	Work Card	Airframe	18-Feb-2009 H: 10080.00	M: 24			18-Feb-2011	M: 12 D: 9



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
57 L5710035-02	INSP RIGHT WING INBD DRY BAY	Work Card		18-Feb-2009 H: 10080.00	M: 24			18-Feb-2011	M: 12 D: 9
124			Airframe						
71 71E1MPI	MPI NO.1 ENGINE	Work Card		17-Jun-2008 H: 9763.00	H: 1400			H: 11163.00	H: 1036.90
266			Engine 1						
71 71E2MPI	MPI NO.2 ENGINE	Work Card		14-Apr-2007 H: 8392.90	H: 1400			H: 9792.90	H: 352.20
289			Engine 2						
71 E7120029-01	MAG PART INSP NO.1 ENG FWD/AFT MNT CAST/ISOL & HARDWARE (PRE 35/36-71-5)	Work Card						30-Oct-2015 L: 12,278.00	M: 68 D: 21 L: 4310
76			Airframe						
71 E7120029-02	MAG PART INSP NO.2 ENG FWD/AFT MNT CAST/ISOL & HARDWARE (PRE 35/36-71-5)	Work Card						30-Oct-2015 L: 12,278.00	M: 68 D: 21 L: 4310
77			Airframe						
71 E7120034-01	FPI NO.1 ENG FWD MNT CAST ATTACH BOLTS (POST 35/36-71-5)	Work Card						30-Oct-2015 L: 12,278.00	M: 68 D: 21 L: 4310
74			Airframe						
71 E7120034-02	FPI NO.2 ENG FWD MNT CAST ATTACH BOLTS (POST 35/36-71-5)	Work Card						30-Oct-2015 L: 12,278.00	M: 68 D: 21 L: 4310
75			Airframe						
71 E7120038-01	REPL NO.1 ENG FWD MNT ATCH BOLTS (2651026)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
155			Airframe						
71 E7120038-02	REPL NO.2 ENG FWD MNT ATCH BOLTS (2651026)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
156			Airframe						
71 E7120039-01	REPL NO.1 ENG AFT ATCH BOLTS (2652002/2651027)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
157			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
71 E7120039-02	REPL NO.2 ENG AFT ATCH BOLTS (2652002/2651027)	Work Card		07-Apr-2005 H: 8883.20 L: 6746	H: 20000			H: 28883.20	H: 18587.60
158			Airframe						
71 E7120040-01	REPL NO.1 ENG FWD UPR/LWR SHK SUP BOLTS(6600187/NAS1307-3H)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
159			Airframe						
71 E7120040-02	REPL NO.2 ENG FWD UPR/LWR SHK SUP BOLTS(6600187/NAS1307-3H)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
160			Airframe						
71 E7120041-01	REPL NO.1 ENG AFT SHK MNT ATCH BOLTS (NAS335CP23)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
161			Airframe						
71 E7120041-02	REPL NO.2 ENG AFT SHK MNT ATCH BOLTS (NAS335CP23)	Work Card		07-Mar-1979	H: 20000			H: 20000.00	H: 9704.40
162			Airframe						
71 EN1	LEFT ENGINE	Work Card							
461	S/N: P-74665		On Condition						
71 EN2	RIGHT ENGINE	Work Card							
462	S/N: P-74904		On Condition						
71 ENG01	NO.1 ENG MPI/AIRFRAME ITEMS	Work Card		04-Jul-2008 H: 9841.80	H: 1400			H: 11241.80	H: 946.20
72			Airframe						
71 ENG02	NO.2 ENG MPI/AIRFRAME ITEMS	Work Card		14-Apr-2007 H: 9247.80	H: 1400			H: 10647.80	H: 352.20
73			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
71 K7120036-01 149	REPL NO.1 ENG FWD UPPER SHK MT COVER(LM-833-3)	Work Card	Airframe	05-Feb-1999 H: 6963.50 L: 4894	H: 4200			H: 11163.50	H: 867.90
71 K7120036-02 150	REPL NO.1 ENG FWD LWR SHK MT COVER(LM-833-3)	Work Card	Airframe	05-Feb-1999 H: 6963.50 L: 4894	H: 4200			H: 11163.50	H: 867.90
71 K7120036-03 151	REPL NO.2 ENG FWD UPPER SHK MT COVER(LM-833-3)	Work Card	Airframe	16-Oct-2001 H: 7780.80 L: 5879	H: 4200			H: 11980.80	H: 1685.20
71 K7120036-04 152	REPL NO.2 ENG FWD LWR SHK MT COVER(LM-833-3)	Work Card	Airframe	16-Oct-2001 H: 7780.80 L: 5879	H: 4200			H: 11980.80	H: 1685.20
71 K7120064-01 163	REPL NO.1 ENG FWD UPR SHK MNT CVR BOLTS (NAS1304-1H)	Work Card	Airframe	05-Feb-1999 H: 6963.50 L: 4894	H: 4200			H: 11163.50	H: 867.90
71 K7120064-02 164	REPL NO.1 ENG FWD LWR SHK MNT CVR BOLTS (NAS1304-1H)	Work Card	Airframe	05-Feb-1999 H: 6963.50 L: 4894	H: 4200			H: 11163.50	H: 867.90
71 K7120064-03 165	REPL NO.2 ENG FWD UPR SHK MNT CVR BOLTS (NAS1304-1H)	Work Card	Airframe	16-Oct-2001 H: 7780.80 L: 5879	H: 4200			H: 11980.80	H: 1685.20
71 K7120064-04 166	REPL NO.2 ENG FWD LWR SHK MNT CVR BOLTS (NAS1304-1H)	Work Card	Airframe	16-Oct-2001 H: 7780.80 L: 5879	H: 4200			H: 11980.80	H: 1685.20
71 L7120037-01 153 P/N: 6600309-3	NO.1 ENGINE AFT ISOLATOR ASSEMBLY S/N: UNK	Work Card	Airframe	H: 6963.50	H: 8400		H: 0.00	H: 15363.50	H: 5067.90



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
71 L7120037-02	NO.2 ENGINE AFT ISOLATOR ASSEMBLY 154 P/N: 6600309-005 S/N: LK1880	Work Card	Airframe	07-Apr-2005 H: 8883.20 L: 6746	H: 8400		H: 0.00	H: 17283.20	H: 6987.60
71 L7120063-01	INSP/CHK NO.1 ENG FWD/AFT MNT ISOL & PARTS 78	Work Card	Airframe	04-Jul-2008 H: 9841.80	H: 1400			H: 11241.80	H: 946.20
71 L7120063-02	INSP/CHK NO.2 ENG FWD/AFT MNT ISOL & PARTS 79	Work Card	Airframe	14-Apr-2007 H: 9247.80	H: 1400			H: 10647.80	H: 352.20
71 L7120065-01	REPL NO.1 ENG FWD UPR SHK MNT ASSY (LM-833-1) 167	Work Card	Airframe	H: 5568.00	H: 8400			H: 13968.00	H: 3672.40
71 L7120065-02	REPL NO.1 ENG FWD LWR SHK MNT ASSY (LM-833-1) 168	Work Card	Airframe	H: 5568.00	H: 8400			H: 13968.00	H: 3672.40
71 L7120065-03	REPL NO.2 ENG FWD UPR SHK MNT ASSY (LM-833-1) 169	Work Card	Airframe	H: 4801.00	H: 8400			H: 13201.00	H: 2905.40
71 L7120065-04	REPL NO.2 ENG FWD LWR SHK MNT ASSY (LM-833-1) 170	Work Card	Airframe	H: 6290.90	H: 8400			H: 14690.90	H: 4395.30
71 L7120066-01	REPL NO.1 ENG FWD UPR SHK MNT HOUSING (LM-833-2) 171	Work Card	Airframe	H: 6963.50	H: 8400			H: 15363.50	H: 5067.90
71 L7120066-02	REPL NO.1 ENG FWD LWR SHK MNT HOUSING (LM-833-2) 172	Work Card	Airframe	H: 8451.70	H: 8400			H: 16851.70	H: 6556.10



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
71 L7120066-03	REPL NO.2 ENG FWD UPR SHK MNT HOUSING (LM-833-2)	Work Card		30-Oct-2003 H: 8451.70 L: 6278	H: 8400			H: 16851.70	H: 6556.10
173			Airframe						
71 L7120066-04	REPL NO.2 ENG FWD LWR SHK MNT HOUSING (LM-833-2)	Work Card		30-Oct-2003 H: 8451.70 L: 6278	H: 8400			H: 16851.70	H: 6556.10
174			Airframe						
71 L7120067-01	FPI NO.1 ENG AFT ATTACH BOLT (P/N 2652002)	Work Card		04-Jul-2008 H: 9841.80	H: 1400			H: 11241.80	H: 946.20
80			Airframe						
71 L7120067-02	FPI NO.2 ENG AFT ATTACH BOLT (P/N 2652002)	Work Card		14-Apr-2007 H: 9247.80	H: 1400			H: 10647.80	H: 352.20
81			Airframe						
71 Q7120072	NO 1 ENG AFT ENGINE ATTACH BOLT (P/N 2652002-3 AND -801) -PERFORM MAGNETIC PARTICLE INSPECTION	Work Card			H: 1400			H: 11,163.00	H: 1036.90
496			Engine 1						
71 Q7120072	NO 2 ENG AFT ENGINE ATTACH BOLT (P/N 2652002-3 AND -801) -PERFORM MAGNETIC PARTICLE INSPECTION	Work Card			H: 1400			H: 9,792.90	H: 352.20
497			Engine 2						
72 060 060	NO. 1 HP TURBINE - SEAL PLATE	Work Card							
485			On Condition						
72 270 270	NO. 2 HP TURBINE - SEAL PLATE	Work Card			C: 10000.00			C: 10000.00	C: 2676.00
486			Engine 2						
72 72E1001	FAN ROTOR DISK NO.1 ENGINE	Work Card		C: 4032.00	C: 10000.00		C: 0.00	C: 14032.00	C: 5904.00
271 P/N: 3073563			Engine 1						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
72 72E1002	1ST STAGE LPC DISK NO.1 ENGINE 272 P/N: 3072395	Work Card	Engine 1		C: 10000.00		C: 0.00	C: 10000.00	C: 1872.00
72 72E1003	2ND STAGE LPC DISK NO.1 ENGINE 273 P/N: 3072396	Work Card	Engine 1		C: 10000.00		C: 0.00	C: 10000.00	C: 1872.00
72 72E1004	3RD STAGE LPC DISK NO.1 ENGINE 274 P/N: 3072397	Work Card	Engine 1		C: 10000.00		C: 0.00	C: 10000.00	C: 1872.00
72 72E1005	4TH STAGE LPC DISK NO.1 ENGINE 275 P/N: 3072398	Work Card	Engine 1		C: 10000.00		C: 0.00	C: 10000.00	C: 1872.00
72 72E1006	HPC IMPELLER NO.1 ENGINE 276 P/N: 3073394-1	Work Card	Engine 1	C: 3242.00	C: 10000.00		C: 0.00	C: 13242.00	C: 5114.00
72 72E1009	1ST STAGE LPT DISK NO.1 ENGINE 279 P/N: 3072076	Work Card	Engine 1	C: 6191.00	C: 4400.00		C: 0.00	C: 10591.00	C: 2463.00
72 72E1010	2ND STAGE LPT DISK NO.1 ENGINE 280 P/N: 3072069	Work Card	Engine 1	17-Jun-2008 C: 7522.00	C: 4500.00		C: 0.00	C: 12022.00	C: 3894.00
72 72E1011	3RD STAGE LPT DISK NO.1 ENGINE 281 P/N: 3072068-1	Work Card	Engine 1	C: 6668.00	C: 9500.00		C: 6668.00	C: 9500.00	C: 1372.00
72 72E1012	HPT ROTOR NO.1 ENGINE 282 P/N: 3072732	Work Card	Engine 1	C: 4807.00	C: 5200.00		C: 0.00	C: 10007.00	C: 1879.00



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
72 72E1AGI 270	ACCESSORY GEARBOX INSPECTION NO.1 ENGINE	Work Card	Engine 1	04-Mar-1999 H: 6885.30 C: 4807.00	H: 4200			H: 11085.30	H: 959.20
72 72E1CZI 268	CZI NO.1 ENGINE	Work Card	Engine 1	04-Mar-1999 H: 6885.30 C: 4807.00	H: 4200			H: 11085.30	H: 959.20
72 72E1FSI 269	FAN SUPPORT INSP NO.1 ENGINE	Work Card	Engine 1	04-Mar-1999 H: 6885.30 C: 4807.00	H: 4200			H: 11085.30	H: 959.20
72 72E1PLN 267	INSPECT PLENUM NO.1 ENGINE	Work Card	Engine 1	17-Jun-2008 H: 9763.00	H: 1400			H: 11163.00	H: 1036.90
72 72E2001 307 P/N: 3073563	FAN ROTOR DISK NO.2 ENGINE	Work Card	Engine 2	C: 3631.00	C: 10000.00		C: 0.00	C: 13631.00	C: 6307.00
72 72E2002 293 P/N: 3072395	1ST STAGE LPC DISK NO.2 ENGINE	Work Card	Engine 2		C: 10000.00		C: 0.00	C: 10000.00	C: 2676.00
72 72E2003 294 P/N: 3072396	2ND STAGE LPC DISK NO.2 ENGINE	Work Card	Engine 2		C: 10000.00		C: 0.00	C: 10000.00	C: 2676.00
72 72E2004 295 P/N: 3072397	3RD STAGE LPC DISK NO.2 ENGINE	Work Card	Engine 2		C: 10000.00		C: 0.00	C: 10000.00	C: 2676.00
72 72E2005 296 P/N: 3075326-3 S/N: 060350106551	4TH STAGE LPC DISK NO.2 ENGINE	Work Card	Engine 2	13-Apr-2007 H: 8392.90 C: 6411.00	C: 10000.00		C: 0.00	C: 16411.00	C: 9087.00





Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
72 72E2006	HPC IMPELLER NO.2 ENGINE 297 P/N: 3073394	Work Card	Engine 2	07-Sep-1994 C: 3234.00	C: 10000.00		C: 3473.00	C: 9761.00	C: 2437.00
72 72E2009	1ST STAGE LPT DISK NO.2 ENGINE 300 P/N: 3072070	Work Card	Engine 2	C: 4039.00	C: 4400.00		C: 0.00	C: 8439.00	C: 1115.00
72 72E2010	2ND STAGE LPT DISK NO.2 ENGINE 301 P/N: 3072069	Work Card	Engine 2	07-Oct-1997 C: 4039.00	C: 4500.00		C: 0.00	C: 8539.00	C: 1215.00
72 72E2011	3RD STAGE LPT DISK NO.2 ENGINE 302 P/N: 302068	Work Card	Engine 2		C: 9500.00		C: 0.00	C: 9500.00	C: 2176.00
72 72E2012	HPT ROTOR NO.2 ENGINE 303 P/N: 3075777-1 S/N: 061217200360	Work Card	Engine 2	13-Apr-2007 H: 8392.90 C: 6411.00	C: 5200.00		C: 0.00	C: 11611.00	C: 4287.00
72 72E2AGI	ACCESSORY GEARBOX INSPECTION 306	Work Card	Engine 2	13-Apr-2007 H: 8392.90	H: 4200			H: 12592.90	H: 3152.20
72 72E2CZI	CZI NO.2 ENGINE 291	Work Card	Engine 2	13-Apr-2007 H: 8392.90 C: 6411.00	H: 4200			H: 12592.90	H: 3152.20
72 72E2FSI	FAN SUPPORT INSP NO.2 ENGINE 292	Work Card	Engine 2	13-Apr-2007 H: 8392.90	H: 4200			H: 12592.90	H: 3152.20
72 72E2PLN	INSPECT PLENUM NO.2 ENGINE 290	Work Card	Engine 2	15-Sep-2003 H: 8372.10 C: 6191.00	H: 1400			H: 9772.10	H: 331.40



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times		Reported Engine Times			Aircraft / Operator Information	
Date	01-Feb-2010	Engine 1:	H: 10126.10	C: 8,128.00	P-74665	Sun Quest
Hours:	10295.60	Engine 2:	H: 9440.70	C: 7,324.00	P-74904	Aircraft: BOMBARDIER LEARJET 35A
Landings:	7,968	Engine 3:			-	Serial Number: 233
		Engine 4:			-	Engine Model: TFE731-2-2B
		APU:			-	

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other								
73	NO. 1 ENGINE - FUEL FILTER	Work Card		15-Aug-2008 H: 9763.00	H: 600		H: 0.00	H: 10363.00	H: 236.90
	493 P/N: 987830-1		Engine 1						
73	NO. 2 ENGINE - FUEL FILTER	Work Card		28-Oct-2008 H: 9156.40	H: 600		H: 0.00	H: 9756.40	H: 315.70
	494 P/N: 897830-1		Engine 2						
78 1TR1400	INSPECT T/R NO.1 ENGINE-1400 HR - 1500 HR	Work Card	N/A	04-Jul-2008					
	318		On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 1TR150	INSPECT T/R NO.1 ENGINE-150 HR - 200 HR	Work Card	N/A	04-Jul-2008					
	312		On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 1TR300	INSPECT T/R NO.1 ENGINE-300 HR - 400 HR	Work Card	N/A	04-Jul-2008					
	314		On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 1TR600	INSPECT T/R NO.1 ENGINE-600 HR - 800 HR	Work Card	N/A	04-Jul-2008					
	316		On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB	Description	Links	Disposition Group	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
Item No.	Part No. / Serial No. / Reference No. / Other		Tracked						
78 2TR1400	INSPECT T/R NO.2 ENGINE-1400 HR - 1500 HR	Work Card	N/A	04-Jul-2008					
319			On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 2TR150	INSPECT T/R NO.2 ENGINE-150 HR - 200HR	Work Card	N/A	04-Jul-2008					
313			On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 2TR300	INSPECT T/R NO.2 ENGINE-300 HR - 400 HR	Work Card	N/A	04-Jul-2008					
315			On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
78 2TR600	INSPECT T/R NO.2 ENGINE-600 HR - 800 HR	Work Card	N/A	04-Jul-2008					
317			On Condition						
	Notes / Compliance	TRS DEACTIVATED IAW STC ST02635AT							
79 79E1OIL	OIL CHANGE NO.1 ENGINE	Work Card		03-Dec-2009 H: 10106.90	H: 600			H: 10706.90	H: 580.80
308			Engine 1						
79 79E2OIL	OIL CHANGE NO.2 ENGINE	Work Card		23-May-2008 H: 8974.40	H: 600			H: 9574.40	H: 133.70
309			Engine 2						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
SB 35/36-28-10	FUEL- INSPECTION OF TIP TANK FLAPPER VALVES	Work Card	N/A	24-Apr-2006					
470			Airframe						
	Notes / Compliance								
	AD 2005-16-09 COMPLIED WITH								
SB 35/36-31-3 R1	INDICATING / RECORDING SYSTEM = INSTALLATION OF CABIN ALTITUDE WARNING SYSTEM (AIRCRAFT WITHOUT AUTO EMERGENCY AIR) (REV 1)	Work Card	OPEN						
499			Airframe						
	Notes / Compliance								
	S/N EFF: 35 002-35 106, 35 108-35 112, 36 002-36 031								
SB 35/36-31-4 R2	INDICATING/RECORDING SYSTEM - INSTALLATION OF CABIN ALTITUDE WARNING SYSTEM (AIRCRAFT WITH AUTO EMERGENCY AIR) 35-107, 35-113 THRU 35-676 (REV 2)	Work Card	OPEN						
501			Airframe						
AD 1974-08-09 R2	LAVORATORIES EQUIPPED WITH PAPER OR LINEN RECEPTACLES	Work Card	RECURRING	22-Aug-2008 H: 9932.50	H: 1000			H: 10932.50	H: 636.90
FAA	244		Airframe						
	Notes / Compliance								
	C/W								
AD 1982-01-05 R2	INSPECT STALL WARNING ACCELEROMETER	Work Card	RECURRING	09-Apr-2009 H: 10115.70 L: 7850	H: 220			H: 10335.70	H: 40.10
FAA	419		Airframe						
	Notes / Compliance								
	C/W								
AD 1987-02-06	LEFT FWD MNT MPI INSP	Work Card	RECURRING	04-Jul-2008 H: 9841.80	H: 1500			H: 11341.80	H: 1046.20
FAA	260		Airframe						
	Notes / Compliance								
	C/W								



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD 1987-02-06	LEFT FWD MNT VISUAL INSP	Work Card	RECURRING	03-Nov-2009 H: 10242.10 L: 7929	H: 420			H: 10662.10	H: 366.50
FAA 258			Airframe						
	Notes / Compliance	C/W AD 1987-02-06							
AD 1987-02-06	RIGHT FWD MNT MPI INSP	Work Card	RECURRING	13-Apr-2007 H: 9247.80	H: 1500			H: 10747.80	H: 452.20
FAA 261			Airframe						
	Notes / Compliance	C/W							
AD 1987-02-06	RIGHT FWD MNT VISUAL INSP	Work Card	RECURRING	05-Jan-2009 H: 10064.80	H: 420			H: 10484.80	H: 189.20
FAA 259			Airframe						
	Notes / Compliance	C/W							
AD 1995-25-03	INSPECT TIP TANK FLAPPER VALVE	Work Card	SUPERSEDED	30-Oct-2003 H: 8451.70 L: 6278					
FAA 418			Airframe						
	Notes / Compliance	SUPERSEDED BY AD 2005-16-09 - N/A DUE TO REPLACEMENT OF VALVES							
AD 2005-05-15 AMD 39-14004	ENGINE NO. 1- INSPECT LPT STAGE 1 NOZZLE ASSEMBLY	Work Card Task Card		17-Jun-2008 H: 9763.00					
FAA 464			Airframe						
AD 2005-05-15 AMD 39-14004	ENGINE NO. 2- INSPECT LPT STAGE 1 NOZZLE ASSEMBLY	Work Card Task Card	COMPLIED WITH	16-Mar-2007 H: 9247.80					
FAA 465			Airframe						



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
AD 2005-13-07 AMD 39-14143	AD 2005-13-07 AMD 39-14143 NO. 1 ENGINE- REPLACE LPT DISCS AS LISTED IN SB TFE731-72-3682	Work Card Task Card	N/A						
FAA	467		Airframe						
	Notes / Compliance	N/A DUE TO MANUFACTURE INSTALL DATE OF 1ST AND 2ND STAGE LPT DISCS							
AD 2005-13-07 AMD 39-14143	AD 2005-13-07 AMD 39-14143 NO. 2 ENGINE- REPLACE LPT DISCS AS LISTED IN SB TFE731-72-3682	Work Card Task Card	N/A						
FAA	468		Airframe						
	Notes / Compliance	N/A DUE TO S/N INSTALLED IN ENGINE							
AD 2005-13-36 AMD 39-14173	DETAILED INSPECTION OF THE CENTER BALL OF THE AILERON CONTROL CABLES	Work Card Task Card	COMPLIED WITH	30-Dec-2005 H: 8889.20					
FAA	466		Airframe						
AD 2005-16-09 AMD 39-14214	AD 2005-16-09 AMD 39-14214 INSPECTION AND REPLACEMENT OF TIP TANK FLAPPER VALVES	Work Card Task Card	COMPLIED WITH						
FAA	469		Airframe						
	Notes / Compliance	TIPTANK FLAPPER VALVES REPLACED 4/24/2006. THIS ACTION TERMINATES REPETIVE 600 HR INSPECTIONS OF TIPTANK FLAPPER VALVES.							
AD 2006-16-18 AMD 39-14718	TO PREVENT A BEARING ERROR WHICH COULD LEAD TO AN AIRPLANE DEPARTING FROM ITS SCHEDULED FLIGHT PATH	Work Card Task Card	N/A						
FAA	483		Airframe						
	Notes / Compliance	N/A BENDIX CAS66A SYSTEM INSTALLED.							
AD 2007-04-18 AMD 39-14950	TO PREVENT INADVERTENT OPERATION OF A STANDBY FUEL PUMP DUE TO AN ELECTRICAL SYSTEM MALFUNCTION	Work Card Task Card	COMPLIED WITH	17-Jun-2008 H: 9763.00					
FAA	484		Airframe						
	Notes / Compliance	AD COMPLIED WITH. SEE LOGBOOK ENTRY DATED 4/4/2007							



Complete Tracked Items

N23A

Report Date: 09-Feb-2010

Reported Aircraft Times

Date: 01-Feb-2010
 Hours: 10295.60
 Landings: 7,968

Reported Engine Times

Engine 1: H: 10126.10 C: 8,128.00 P-74665
 Engine 2: H: 9440.70 C: 7,324.00 P-74904
 Engine 3: -
 Engine 4: -
 APU: -

Aircraft / Operator Information

Sun Quest
 Aircraft: BOMBARDIER LEARJET 35A
 Serial Number: 233
 Engine Model: TFE731-2-2B

REV: LEARJET 35/35A/36/36A MM REVISION 76

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD 2007-17-17 AMD 39-15175	TO PREVENT PENETRATION OF FLAMMABLE LIQUIDS OR FIRE THROUGH ENGINE FIREWALL INTO THE ENGINE PYLON	▶ Work Card ▶ Task Card	COMPLIED WITH	01-Oct-2008 H: 9987.60					
FAA 487			Airframe						
	Notes / Compliance								
	COMPLIED WITH								
AD 2008-02-19 AMD 39-15349	NO. 1 ENGINE- TO PREVENT UNCONTAINED FAILURE OF THE HP TURBINE ROTOR ASSY	▶ Work Card ▶ Task Card	N/A	18-Feb-2008					
FAA 488			Engine 1						
	Notes / Compliance								
	N/A DUE TO PART NO. AND SERIAL NO. INSTALLED								
AD 2008-02-19 AMD 39-15349	NO. 2 ENGINE- TO PREVENT UNCONTAINED FAILURE OF THE HP TURBINE ROTOR ASSY	▶ Work Card ▶ Task Card	N/A	18-Feb-2008					
FAA 489			Engine 2						
	Notes / Compliance								
	N/A DUE TO PART NO. AND SERIAL NO. INSTALLED								

Total Items: 293